

4 结语

我国轮胎正在向高档次、绿色制造、绿色产品方向发展,这给橡胶机械发展提供了极大的挑战和机遇,同时我国橡胶机械经过多年的高速发展,出

现了产能过剩、过分依赖国外市场、环保和安全性有待提高等问题,必须采取产品升级及产品和工艺绿色化、标准化、信息化、国际化的策略,我国橡胶机械才能迎来新发展。

Development Strategy of China's Rubber Machinery Industry in Transition

Zhou Baodi, Chen Weifang

(Guilin Rubber Machinery Factory, Guilin 541002, China)

Abstract: In this paper, the development strategy of China's rubber machinery industry was presented. In order to meet the development of the tire industry, reduce excess capacity, reduce external dependence, and drive green tire growth, China's rubber machinery industry must upgrade the product portfolio, promote green technology, implement information technology, and accelerate standardization and globalization.

Keywords: rubber machinery; tire; upgrade; green technology; standardization; information technology; globalization



信息·资讯

大陆轮胎公司召回一批原配子午线轮胎

大陆轮胎美洲公司宣布召回近6000条商品名为ProContact GX SSR的子午线轮胎。这批轮胎主要用作2015年新款梅赛德斯-奔驰C级车的原配轮胎,同时已有约100条轮胎在替换轮胎市场售出。

大陆公司表示,这批被召回的轮胎规格为225/45R1895H XL,是由其在美国伊利诺伊州芒特弗农(Mount Vernon)的轮胎工厂于2014年6月22日至7月28日生产的,美国交通运输部的轮胎识别代码(DOT TIN)为A34F WBJR 2514~3014。

导致这批问题轮胎的原因是1台硫化机出现间歇性故障,活络模未能完全伸展,这批轮胎在硫化过程中可能发生了变形,在充气后轮胎胎面可能会呈现扭曲状态。这批轮胎在使用过程中可能会突然出现故障,发生交通事故的风险增大。尽管公司目前尚未收到这批轮胎的任何故障报告,但是已通知车主和轮胎经销商到梅赛德斯-奔驰汽车经销商处免费更换轮胎。

国 艺